



RECALL NOTICE
3M™ Peltor™ LiteCom Pro II Ex: MT7H7*4010-EU-50

November 13, 2013

Dear Valued 3M Customer:

We recently identified that a limited number of 3M™ Peltor™ LiteCom Pro II , part number MT7H7*4010-EU-50, were delivered with the incorrect battery “ACK081”. As a result, the **product cannot be used in ATEX areas and must be removed from service immediately**. In addition, the charger cable “AL2AH” will fail while charging with the ACK081 battery, and will no longer charge properly. .

For this reason, 3M requests that you take the following steps:

- Locate any headsets with serial numbers listed above.
- Workers must stop using the headset immediately especially in potentially explosive atmospheres.
- Please contact Lars Reibner (contact details as below) to arrange for replacement of affected battery and charger cable.
- Replace the battery with model “ACK08” battery and start using the new AL2AH charger cable.
- Confirm with 3M that the battery has been replaced. Customer service will follow up by phone to confirm the battery has been replaced.

We want to emphasize that this deviation is limited only to the serial numbers listed below.

Art nr	Prod order	Serial nr
MT7H7F4010-EU-50	30608472	3613176681
MT7H7F4010-EU-50	30608472	3613176705
MT7H7F4010-EU-50	30608472	3613176706
MT7H7F4010-EU-50	30608472	3613176707
MT7H7F4010-EU-50	30608472	3613176708
MT7H7F4010-EU-50	30608472	3613176709
MT7H7F4010-EU-50	30608472	3613176710
MT7H7F4010-EU-50	30608472	3613176711
MT7H7F4010-EU-50	30608472	3613176712
MT7H7F4010-EU-50	30608472	3613176713
MT7H7F4010-EU-50	30608472	3613176714
MT7H7F4010-EU-50	30608472	3613176715
MT7H7F4010-EU-50	30608472	3613176716
MT7H7F4010-EU-50	30608472	3613176717
MT7H7F4010-EU-50	30608472	3613176718
MT7H7F4010-EU-50	30608472	3613176719
MT7H7F4010-EU-50	30608472	3613176720
MT7H7F4010-EU-50	30608472	3613176721
MT7H7F4010-EU-50	30608472	3613176722
MT7H7F4010-EU-50	30608472	3613176723
MT7H7P3E4010-EU-50	30630864	4313167847
MT7H7P3E4010-EU-50	30630864	4313167864
MT7H7P3E4010-EU-50	30630864	4313167866
MT7H7P3E4010-EU-50	30630864	4313167889
MT7H7P3E4010-EU-50	30630864	4313167905
MT7H7P3E4010-EU-50	30630864	4313167909
MT7H7P3E4010-EU-50	30630864	4313167910
MT7H7P3E4010-EU-50	30630864	4313167911
MT7H7P3E4010-EU-50	30630864	4313167912
MT7H7P3E4010-EU-50	30630864	4313167913
MT7H7P3E4010-EU-50	30630864	4313167914
MT7H7P3E4010-EU-50	30630864	4313167915
MT7H7P3E4010-EU-50	30630864	4313167916
MT7H7P3E4010-EU-50	30630864	4313167917
MT7H7P3E4010-EU-50	30630864	4313167918
MT7H7P3E4010-EU-50	30630864	4313167919
MT7H7P3E4010-EU-50	30630864	4313167920
MT7H7P3E4010-EU-50	30630864	4313167921
MT7H7P3E4010-EU-50	30630864	4313167922
MT7H7P3E4010-EU-50	30630864	4313167923
MT7H7P3E4010-EU-50	30630864	4313167924
MT7H7P3E4010-EU-50	30630864	4313167925
MT7H7P3E4010-EU-50	30630864	4313167926
MT7H7P3E4010-EU-50	30630864	4313167927
MT7H7P3E4010-EU-50	30630864	4313167928
MT7H7P3E4010-EU-50	30630864	4313167929
MT7H7P3E4010-EU-50	30630864	4313167930
MT7H7P3E4010-EU-50	30630864	4313167931
MT7H7P3E4010-EU-50	30630864	4313167932

Please contact Lars Reibner, After Market Technician, at: +46 370 69 42 00 to arrange for replacement and return of batteries and cables.
Affected products shall be returned to:

3M Peltor
Att Lars Reibner
Ingelundvägen 21
331 21 VÄRNAMO
SWEDEN

3M regrets any inconvenience that this situation may cause. If you have any questions regarding this issue, please see contact information below.

3M Contact Information:

Fredrik Johansson + 46 370 65 65 95
Ulrik Svensson + 46 370 69 42 67
Niels Hertz + 46 370 69 42 00

Global Product Manager
Global Portfolio Manager
Site Manager

Sincerely,



Ulrik Svensson
3M Personal safety Division, Communication Solutions
Global Portfolio Manager